

11/08/2016 - deburring side skins - 2h

Category: 3.9. Forward and Center fuselage

Published: Friday, 12 August 2016 13:48

Hits: 1358

Put in another two hours last and deburred drilled holes on both left and right, front and back side of the F770 side skins.

Damned, there's a lot of them...

