



Started working on the passenger side canopy skirt and following the same procedure as on the pilot side.



Drilled the top line along the side bow.



Good alignment in the front.



Measured the height from the bow to double check alignment.

